



QUICKSILVER® LIFETIME WARRANTY

The QuickSilver® industrial dump body liner material is warranted to the original purchaser to be free from defects in material and workmanship, including the fusion weld seam, under normal use and service from the date of proper installation for the lifetime of the liner down to within 1/8" remaining liner material. QuickSilver® liners in 1/2" or thicker gauge are warranted for any temperature asphalt. This warranty does not apply to the design or workmanship of the installation or application performance.

The warranty is expressly limited to the replacement or repair of QuickSilver® products at a QuickSilver® authorized dealer location, or such other place as Quadrant EPP may designate. All QuickSilver® liners or parts of QuickSilver® liners returned to Quadrant EPP, or to a location designated by Quadrant EPP for factory inspection of possible defects in workmanship or material, shall be sent with all transportation charges prepaid.

This warranty does not apply to any QuickSilver® liner material of Quadrant EPP which has been repaired or altered outside of Quadrant EPP or which has been installed or used other than in accordance with the printed instructions for QuickSilver® liners from Quadrant EPP. **NO EMPLOYEE OR REPRESENTATIVE IS AUTHORIZED TO CHANGE THIS WARRANTY IN ANY WAY OR GRANT ANY OTHER WARRANTY.**

This warranty does not obligate Quadrant EPP to bear the cost of labor in replacing defective parts. No other obligation is assumed or authorized to be assumed with respect to other products of Quadrant EPP other than herein set forth.

OTHER THAN STATED ABOVE, Quadrant EPP DOES NOT ASSUME ANY OTHER LIABILITY, INCLUDING BUT NOT LIMITED TO, LIABILITY FOR SECONDARY CHARGES, EXPENSES FOR INSTALLATION OR REMOVAL, OR ANY OTHER CONSEQUENTIAL LOSSES OR DAMAGES.

QUADRANT EPP MAKES NO OTHER WARRANTY, EXPRESS OR IMPLIED, AND MAKES NO WARRANTY OF MERCHANTABILITY OR OF FITNESS FOR ANY PARTICULAR PURPOSE.

QuickSilver® Linings from Quadrant Engineering Plastic Products
2120 Fairmont Avenue
PO Box 14235
Reading, PA 19612-4235
Tel. 724 468 7096

QuickSilver® is a registered trademark of the Quadrant group of companies.



PREVENTIVE MAINTENANCE

After a proper installation of your QuickSilver® liner, attention to the following areas of preventative maintenance will help maintain the performance and extend the life of your liner.

- **Liner Trapped Under Leading Edge Protector**
If the liner is not allowed to expand freely, buckling will occur. Periodically check for and remove bends, dents or kinks in the leading edge protector. It's also important to remove bulk materials that may have become lodged between the protector and liner. These conditions could "trap" the liner, preventing movement needed for thermal expansion.
- **Material Trapped Under Liner**
Material under the liner will cause accelerated wear and can cause holes in the liner. Fines can accumulate during unloading or tailgate closing. Check daily for fines under the liner and remove them.
- **Asphalt Emulsion Build-up on Liner**
Bulk materials can stick to emulsion build-up. Emulsion used as an asphalt binder can accumulate on the liner. Use a chemical release agent (check local regulations for proper usage), or rotate asphalt with abrasive loads to wear away the build-up. Detergent based release agents are not recommended.
- **Liner Buckling**
Incorrect loading patterns of hot products can cause buckling and liner failure. Dropping the first load in the center can cause buckling of the liner towards the front. To reduce the risk, place the first dump in the very front of the body (on the doghouse). Subsequent loads should be front to back.
- **Hauling Asphalt**
QuickSilver® liners in ½" or thicker gauge are warranted for any temperature asphalt. QuickSilver® liners in gauges less than ½" are not designed to handle hot asphalt. Doing so will cause performance problems and invalidate the warranty.

LINER FAILURES CAUSED FROM IMPROPER USE, MAINTENANCE OR INSTALLATION ARE NOT COVERED UNDER THE WARRANTY.

If you have any questions about the performance of your QuickSilver® liner, please contact your authorized dealer.



DURAPRO 5 YEAR WARRANTY

The DURAPRO industrial dump body liner material is warranted to the original purchaser to be free from defects in material and workmanship, including the fusion weld seam, under normal use and service for a period of 60 months from the date of proper installation, or to within 1/8" remaining liner material, whichever comes first. **DURAPRO is not designed for use in Asphalt applications.** This warranty does not apply to the design or workmanship of the installation or application performance.

The warranty is expressly limited to the replacement or repair of DURAPRO products at a DURAPRO authorized dealer location, or such other place as Quadrant EPP may designate. All DURAPRO liners or parts of DURAPRO liners returned to Quadrant EPP, or to a location designated by Quadrant EPP for factory inspection of possible defects in workmanship or material, shall be sent with all transportation charges prepaid.

This warranty does not apply to any DURAPRO liner material of Quadrant EPP which has been repaired or altered outside of Quadrant EPP or which has been installed or used other than in accordance with the printed instructions for DURAPRO liners from Quadrant EPP. **NO EMPLOYEE OR REPRESENTATIVE IS AUTHORIZED TO CHANGE THIS WARRANTY IN ANY WAY OR GRANT ANY OTHER WARRANTY.**

This warranty does not obligate Quadrant EPP to bear the cost of labor in replacing defective parts. No other obligation is assumed or authorized to be assumed with respect to other products of Quadrant EPP other than herein set forth.

OTHER THAN STATED ABOVE, Quadrant EPP DOES NOT ASSUME ANY OTHER LIABILITY, INCLUDING BUT NOT LIMITED TO, LIABILITY FOR SECONDARY CHARGES, EXPENSES FOR INSTALLATION OR REMOVAL, OR ANY OTHER CONSEQUENTIAL LOSSES OR DAMAGES.

QUADRANT EPP MAKES NO OTHER WARRANTY, EXPRESS OR IMPLIED, AND MAKES NO WARRANTY OF MERCHANTABILITY OR OF FITNESS FOR ANY PARTICULAR PURPOSE.

DURAPRO Linings from Quadrant Engineering Plastic Products
2120 Fairmont Avenue
PO Box 14235
Reading, PA 19612-4235
Tel 724 468 7096



PREVENTIVE MAINTENANCE

After a proper installation of your DURAPRO liner, attention to the following areas of preventative maintenance will help maintain the performance and extend the life of your liner.

- **Liner Trapped Under Leading Edge Protector**
If the liner is not allowed to expand freely, buckling will occur. Periodically check for and remove bends, dents or kinks in the leading edge protector. It's also important to remove bulk materials that may have become lodged between the protector and liner. These conditions could "trap" the liner, preventing movement needed for thermal expansion.
- **Material Trapped Under Liner**
Material under the liner will cause accelerated wear and can cause holes in the liner. Fines can accumulate during unloading or tailgate closing. Check daily for fines under the liner and remove them.
- **Hauling Asphalt**
DURAPRO liners are not designed to handle hot asphalt. Doing so will cause performance problems and invalidate the warranty.

LINER FAILURES CAUSED FROM IMPROPER USE, MAINTENANCE OR INSTALLATION ARE NOT COVERED UNDER THE WARRANTY.

If you have any questions about the performance of your DURAPRO liner, please contact your authorized dealer.